



April 01, 2015

TIMCO Engineering

Subject: Response letter to JOB 2322UC14 - Cross Match Technologies

This application has been held for months because the modules included in the host device did not meet the SAR requirements for use in a hand held device.

The client has since performed SAR testing on these modules and obtained a change in identification for each module and a class II permissive change for each module. The original FCC identifiers for these modules were TFB-TIW11-01 and QIPPHS8-P. The new FCC identifiers for these models are Q9YSENTRY2 and Q9YSENTRY3.

Please find the following uploaded exhibits to support these changes:

- 1) Q9PSENTRY1 731 Form Rev c.doc . **per request:** 731 Form: Item 12(b) must be marked as yes, and item 12(c) must list the FCCIDs of the two co-located modules and the box checked for "has been granted under FCCIDs listed to the right".
- 2) Q9PSENTRY1 Label Example REV B.pdf

Should you have any questions or concerns, please feel free to contact me directly.

Regards,

A handwritten signature in black ink that reads "Steven E. Hoke".

Steven Hoke
EMC Site Manager