

RE: Broadcom Corporation, FCC ID: QDS-BRCM1022, Assessment NO.: AN07T7245, Notice#1 [Inbox](#)

 from **September Radecki** <september.radecki@ccsemc.com>

[hide details](#) Nov 5 (21 hours ago)    [Reply](#)

to "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>

cc Sunny Shih <sunny.shih@ccsemc.com>

date Nov 5, 2007 6:48 PM

subject RE: Broadcom Corporation, FCC ID: QDS-BRCM1022, Assessment NO.: AN07T7245, Notice#1

Hi Tim,

Below are the answers to your questions on this application.

Q1. The user manual does not contain RF exposure information. Please revise the user manual.

<CCS ANSWER:> Please see attached FCC regulatory statements to be inserted into user manual.

Q2. The user manual does not include a statement advising that use of 5.15-5.25 GHz is limited to indoor operation only. Please revise the user manual.

<CCS ANSWER:> Please see attached FCC regulatory statements to be inserted into user manual.

Q3. Pages 150-155 include instructions for removal and installation of the device. This is in conflict with the grant conditions. Please revise the user manual.

<CCS ANSWER:> Please see attached bios lock document and Request for Confidentiality which address this question.

Thanks and best regards,

September

-----Original Message-----

From: Timothy M. Dwyer

Sent: Monday, October 08, 2007 2:38 PM

To: September Radecki

Cc: Timothy M. Dwyer; Sunny Shih

Subject: Broadcom Corporation, FCC ID: QDS-BRCM1022, Assessment NO.:

AN07T7245, Notice#1

Hello September,

The review for this application is complete. Please reply to the following items.

Q1. The user manual does not contain RF exposure information. Please revise the user manual.

Q2. The user manual does not include a statement advising that use of 5.15-5.25 GHz is limited to indoor operation only. Please revise the user manual.

Q3. Pages 150-155 include instructions for removal and installation of the device. This is in conflict with the grant conditions. Please revise the user manual.

Best regards,

Tim Dwyer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

3 attachments — [Download all attachments](#)

 **Dell_System_ID_lock_v0.3_Theory of Operations.pdf**

135K [View as HTML](#) [Download](#)

 **FCC regulatory statements.pdf**

61K [View as HTML](#) [Download](#)

 **Confidentiality Request QDS-BRCM1022.pdf**

19K [View as HTML](#) [Download](#)