

Report No.: 039261  
Model No.: N/A

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

PLT: 17.36ms


-0.01dB

RB 3MHz#

AT 10dB

RLV: 87.00dBuV

VB 3MHz



Tested By: (Gary Li)

Date: 30-7-03

Checked By: (Van)

Date: 1/8

Test Result: Pass / Fail / NA

DT: 0us

TS: 70ms

F: 49.861300MHz

Report No.: 0397261  
Model No.: N/A

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

PLT: 17.46ms


0.03dB

RB 3MHz#

AT 10dB

RLV: 87.00dBuV

VB 3MHz



DT: 0us

TS: 30ms

F: 49.861300MHz

Tested By: *[Signature]*

Date: 30-7-03

Checked By: *[Signature]*

Date: 1/8

Test Result : Pass / Fail / NA

# INTERTEK TESTING SERVICES

Report No.: 0399261  
Model No.: NH

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

DLT: 1.36ms


0.08dB

RB 3MHz

AT 10dB

RLV: 87.00dBuV

VB 3MHz



Tested By: [Signature]

Date: 30-7-03

Checked By: [Signature]

Date: 1/8

Test Result: Pass / Fail / NA

DT: 0us

TS: 30ms

F: 49.851300MHz

# INTERTEK TESTING SERVICES

Report No.: 0309261  
Model No.: N/A

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement

PLT: 420us


0.04dB

RB 3MHz

AT 10dB

RLV: 87.00dBuV

VB 3MHz



Tested By: (Signature)

Date: 30-7-03

Checked By: (Signature)

Date: 1/8

Test Result : Pass / Fail (NA)

DT: 0us

TS: 30ms

F: 49.861300MHz