

Mike Kuo

From: ting@ccsemc.com.tw
Sent: June29日2004年Tuesday 2:54 AM
To: Mike Kuo
Cc: wklo@ccsemc.com.tw; ting@ccsemc.com.tw
Subject: RE: Misiu System LLC, FCC ID: QGP-RG4102-1, Assessment NO.: AN04 T3968

Hi Mike,

Page 14 limits for fundamental is not correct. Please make necessary correction.

[Ans: The test report is re-done. Please refer to Page 14 of the attached.](#)

Best regards,
Ting

----- 轉呈者 ting/ccsemc 於 2004/06/29 05:34 PM -----

Mike Kuo <MKUO@CCSEMC.com>

2004/06/19 10:19 AM

收件人: ""wklo@ccsemc.com.tw"" <wklo@ccsemc.com.tw>, Mike Kuo <MKUO@CCSEMC.com>
副本抄送: harris@ccsemc.com.tw, cert@ccsemc.com.tw, ting@ccsemc.com.tw
主旨: RE: Misiu System LLC, FCC ID: QGP-RG4102-1, ?Assessment NO.: AN04 ? ? ? ? ? ?T3968

[Hi W. K. :](#)

[Page 14 limits for fundamental is not correct. Please make necessary correction.](#)

[M.Kuo](#)

-----Original Message-----

From: wklo@ccsemc.com.tw [mailto:wklo@ccsemc.com.tw]
Sent: Thursday, June 17, 2004 10:09 PM
To: Mike Kuo
Cc: harris@ccsemc.com.tw; cert@ccsemc.com.tw; ting@ccsemc.com.tw
Subject: FW: Misiu System LLC, FCC ID: QGP-RG4102-1, Assessment NO.: AN04 T3968

Hi Mike,

Please refer to the following for our replies. Thank you for your advice.

Best Rgds,
WK

Mike Kuo <MKUO@CCSEMC.com>

2004/06/16 03:40 PM

收件人: "CCS-Taiwan, Ting (E-mail)" <ting@ccsemc.com.tw>, "CCS-Taiwan, Wklo (E-mail)" <wklo@ccsemc.com.tw>
副本抄送:
主旨: FW: Misiu System LLC, FCC ID: QGP-RG4102-1, ?Assessment NO.: AN04 ? ? ? ?T3968

7/1/2004

-----Original Message-----

From: Compliance Certification Services [mailto:MKuo@ccsemc.com]

Sent: Wednesday, June 16, 2004 12:22 AM

To: mkuo@ccsemc.com

Subject: Misiu System LLC, FCC ID: QGP-RG4102-1, Assessment NO.: AN04T3968

Question #1: The fundamental frequency for this device is 915MHz. Page 14 of test report is below 1GHz measurement but there is no fundamental frequency field strength. Page 16 listed fundamental field strength but without the FCC limits listed. Please make necessary correction.

Ans #1: Correction is made. Please refer to the revised test report below.

Question #2: FCC ID label format uses FCC DoC log for this transceiver, please explain why FCC DoC logo shall be used on this transceiver.

Ans #2: The FCC DoC logo is removed. Please refer to the revised label sample below.

Question #3: User manual or FCC ID label format does not contain information required per section 15.19 (a)(3) of FCC rules. Please provide revised document.

Ans #3: The required information is placed in the revised user manual below.

Best Regards

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

7/1/2004