


Prüfbericht - Nr.: 17002468 001
Test Report No.


Seite 2 von 17
Page 2 of 17

Appendix D
Spurious Emission at Antenna Terminal
Measurements
According to CFR 47 (FCC) part 2.1051


Measurement Result at Block Edge Channel 25(1931.25MHz)




Channel 275(1943.75MHz)




Channel 325(1946.25MHz)




Channel 875(1973.75MHz)



Channel 925(1976.25MHz)






Channel 1175(1988.75MHz)







Measurement Result Outband Band Edge

Channel 25
















Channel 1175










ACPR Test according to EIA/TIA 97D-2001

Channel 1000



Prüfbericht - Nr.: 17002468 001
Test Report No.

Seite 18 von 17
Page 18 of 17

