

Prüfbericht - Nr.: 17002468 001
Test Report No.


Seite 1 von 28
Page 1 of 28


Appendix E
Field Strength of Spurious Radiation
Measurements
According to CFR 47 (FCC) part 2.1053


The Result of Spurious Radiation Test

1. BTS3601 Test Result


One carriers have been work normally. BTS work at frequency No.1000(1980.00MHz)








The point which exceeds the limit line is the carrier frequency.





The Result of Substitute Test




2. ODU3601 Test Result


One carriers have been work normally. BTS work at frequency
No.1000(1980.00MHz)








The point which exceeds the limit line is the carrier frequency.



The Result of Substitute Test



END