



Date: 13 June, 2011

To: Timco Engineering Inc.
849 N.W. State Road 45
P.O. Box 370
Newberry, Florida 32669

To Timco Engineer,

We require to supersede a FCC SAR report (FCC ID: QISU8650NFC-1) which has been granted on June 9th, 2011 .

The reasons to supersede the original SAR report are:

1. Hardware and Software version was wrong, the corrected HW&SW version should be:

HW:	HD1U865M
SW:	HUAWEI U8650-1 V100R001C00B820

2. The original SAR report does not include WIFI hotspot test items. We add WIFI hotspot test in the updated SAR report;

3. SAR body max. value was 0.937W/Kg in original report, but the max. value of body SAR is 0.946W/kg in updated report.

Please kindly list the updated SAR report in FCC website very soon!

Thank you!

Sincerely,

A handwritten signature in black ink that reads "Wu Xuewen".

Xuewen.Wu
Certification Manager
Shenzhen Morlab Communications Technology Co., Ltd.