

# **TIMCO ENGINEERING INC.**

849 NW State Road 45  
Newberry, Florida 32669  
<http://www.timcoengr.com>  
888.472.2424 F 352.472.2030 email: [tei@timcoengr.com](mailto:tei@timcoengr.com)

September 13, 2002

FCC

SUBJECT: HUGEWIN ELECTRONIC (TAIWAN) CO., LTD. FCC ID: QKUHXTC-3001

REFERENCE: JOB #: 784TC2

To whom it may concern:

While reviewing this job, the customer requested a new Grantee Code. The Test Laboratory updated all documents, including FCC Label, etc., to include the new Grantee Code. However, the page number of the Test Report, which is located on the bottom right hand corner of each page, was overlooked. All other documents were updated correctly. For your information, the old (incorrect) Grantee Code was: QHT.

Sincerely,  
Frank (for)

Sid Sanders