

CHANGE IN IDENTIFICATION OF EQUIPMENT
Original FCC ID: FBI910402010
New FCC ID: QLR-910402010
Original Model#: TX-37A
New Model#: TX-37A

Test Report: 73-7791
Page 3 of 9

Front View of the TX-37A:



CHANGE IN IDENTIFICATION OF EQUIPMENT
Original FCC ID: FBI910402010
New FCC ID: QLR-910402010
Original Model#: TX-37A
New Model#: TX-37A

Test Report: 73-7791
Page 4 of 9

Back View of the TX-37A:



CHANGE IN IDENTIFICATION OF EQUIPMENT
Original FCC ID: FBI910402010
New FCC ID: QLR-910402010
Original Model#: TX-37A
New Model#: TX-37A

Test Report: 73-7791
Page 5 of 9

Bottom View of the TX-37A showing the Label:



CHANGE IN IDENTIFICATION OF EQUIPMENT

Original FCC ID: FBI910402010

New FCC ID: QLR-910402010

Original Model#: TX-37A

New Model#: TX-37A

Test Report: 73-7791

Page 6 of 9

Top View of the TX-37A:



CHANGE IN IDENTIFICATION OF EQUIPMENT
Original FCC ID: FBI910402010
New FCC ID: QLR-910402010
Original Model#: TX-37A
New Model#: TX-37A

Test Report: 73-7791
Page 7 of 9

Side View of the TX-37A:

