



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 18, 2006

RE: FCC ID: QMNRM-124_ATCB002939
Attention: Ronald Chernus

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that the documentation states the device is also a BT transceiver. Please provide the 731 for the BT device.
2. Please note that all of the schematics do not appear to have been uploaded. Only the GPs receiver schematics appear to have been provided. Please provide all appropriate schematics.
3. FYI – no action needed for certification on the part 22/24 and BT other than the FCC ID application not applying to nor cover the part 15B portion. Please note that the device has PC connectivity and connects to a PC using a USB port. The 15B unintentional radiator should be properly addressed and labeled per 47CFR parts 2 and 15.
4. Please note that the manual does not contain the required 2 condition statement per 47CFR 15.19. It has been mentioned that the statement in the manual has been accepted by the FCC as compliance to this requirement, however, no evidence of this exemption has been provided. Please either provide a manual with the correct compliance statements or alternately, please provide a copy of the FCC letter stating acceptance of the existing statement in meeting the verbatim required statement of 15.19. Please also note that the IC requires a similar statement in the manual per RSS-GEN section 5.2.
5. Please note that AMPS channel 384 occupied bandwidth appears to fail the emissions mask as shown on page 15 of the report "QMNRM_124_Exhibit_6_WR1021_FCC_CE_AMPS_Occ_BW_Test_Report_1.pdf." Please explain and please provide compliant OBW plot data.
6. Please note that the 731 form and the manual state that HAC is a part of this application. Please note that it does not appear that the HAC report has been provided. Please provide the HAC test report for this product.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.