

Report No.: 0309765  
Model No.: 2350

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

DLT: 20.00ms


-0.03dB

RB 3MHz#

AT 10dB

RLV: 107.00dBuV

VB 3MHz



Tested By: LR  
( Kenneth Wong )

Date: 18/6/03

Checked By: [Signature]  
( Ivan )

Date: 19/6

Test Result : Pass / Fail / NA

DT: 0us

TS: 50ms

F: 27.145600MHz

Report No.: 0309765  
Model No.: 2350

Pursuant to FCC Part 15 Section 15.223 Emissions Requirement

PLT: 19.98ms


0.01dB

RB 3MHz

AT 10dB

RLV: 107.00dBuV

VB 3MHz



Tested By: LR  
( Kenneth Wong )

Date: 18/6/03

Checked By: [Signature]  
( 100 )

Date: 19/6

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.145600MHz

Report No.: 0309765  
Model No.: 2350

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement


DLT: 840us

-0.09dB

RB 3MHz# AT 10dB

RLV: 107.00dBuV

VB 3MHz



Tested By: KR  
( Kenneth Wong )

Date: 18/6/03

Checked By: [Signature]  
( [Signature] )

Date: 19/6

Test Result : Pass / Fail / NA

DT: 0us

TS: 30ms

F: 27.145600MHz

# INTERTEK TESTING SERVICES

Report No.: 0309765  
Model No.: 2350

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

PLT: 240us


-0.02dB

RB 3MHz#

AT 10dB

RLV: 107.00dBuV

VB 3MHz



DT: 0us

TS: 30ms

F: 27.145600MHz

Tested By: KK  
( Kenneth Wong )

Date: 8/16/03

Checked By: [Signature]  
( [Signature] )

Date: 19/6

Test Result : Pass / Fail / NA