



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

December 26, 2007

RE: FCC ID: QTLRM-391_ATCB005765

Attention: Yao Shuo-Lisa

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that other than the phone serial number the reference to HAC in one and the date of test, I cannot adequately tell the reasons for the different reports. While I can assume one is for a device with HAC and one is for a device without HAC, I cannot tell if this is the actual reason. Perhaps the one report is to perform erp/eirp on the phone HAC is to be performed. I do not know. Please explain why two separate reports for radiated power have been provided and please explain the difference.
2. Please provide the analyzer setting (i.e. res bw, vid bw etc) for the BT test report conducted spurious emissions in test report "Exhibit_6_RM-391_Cph_FCC_0748_05_15C_outputpower.pdf."



Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.