



Ref: US.000288

22nd July 2009

To FCC

BABT
Balfour House, Churchfield Road
Walton on Thames
Surrey, KT12 4TD
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201

Direct Dial: +44 (0)1932 251230
E-mail: Tom.Twynam@babt.com
Website: www.babt.com

Evaluation of Dyson DC22
FCC id: QVHDC22TXUS

I have assessed the above referenced submission for Dyson Ltd and found it to be compliant. The product is a vacuum cleaner remote control. There are two models Motorhead and Turbine which are electrically identical. The former has an additional button for control of the brush head.

The following points were noted and resolved during the evaluation.

1. User Manual

There was no label showing the location of the FCC label on the product. A further photograph was supplied to correct this.

2. Block Diagram

A block diagram was not provided in respect of the part 15B receiver which is located in the body of the vacuum cleaner. This was subsequently provided.

Yours sincerely

A handwritten signature in blue ink, reading 'T. J. Twynam'.

Tom Twynam
Technical Certifier
For BABT TCB