



730 The Kingsway
Peterborough
ON K9J 6W6
Canada
Email: general@abmsensor.com
Web: www.abmsensor.com
Ph: (705)740-2010
Fax: (705)740-2010

To Whom it may concern 11Feb/03

To eliminate leakage from the power cable and the rod antenna and housing transition we made the following modifications:

1. 100pF capacitors between the AC lines and ground
2. Gap between the antenna and the enclose was eliminated by putting conductive foil made of Aluminum or SS in the transition between the enclose and the rod antenna.

The above methods will be implemented on all production units.

Regards,

Bogdan Cherek, President of ABM Sensor Technology