

Correspondence by Project

Project Number:

-177483602

Correspondence Number	Memo
QY4AVT9003A-1	1) Changes were made to the application to indicate correct frequency range. 2) Video Average procedure was used to take average measurements. 3) Yes. Both modes were tested. 4) Connector type of the antenna used was SMA.
Correspondence Number	Memo
QY4AVT9003A-1	Mr. McCutchan, In response to your e-mail, I am addressing each issue in the order received. 1) The form 731 was modified to correct the frequency range as requested. 2) The averaging procedure is included in the report in section 7.1.5 3) The description of the configurations tested is also in the report section 4.1. 4) The antenna connector is a reverse polarity SMA connector. Please see the newly uploaded report A61205F1. Best Regards, Ruby A. Hall