



BABT  
Claremont House, 34 Molesey Road  
Walton on Thames  
Surrey, KT12 4RQ  
United Kingdom  
Telephone: +44 (0)1932 251200  
Fax: +44 (0)1932 251201

Ref: US000087

25 October 2004

To FCC

Direct Dial: +44 (0)1932 251247  
E-mail: [bill.wilson@babt.com](mailto:bill.wilson@babt.com)  
Website: [www.babt.com](http://www.babt.com)

**Evaluation of Newgen N541**  
**FCC id: R5WNGTN541T**

I have assessed the submission and find it compliant.

The following were noted and resolved during the evaluation.

- 1: The Part 22, 24 test report contained typing errors which appeared to place one test frequency outside the permitted band. A revised report was supplied.
- 2: Covering letters were not obviously from the applicant and were not addressed to BABT. Replacement letters were provided.
- 3: The operational description provided was for a different model. A revised description was supplied.

Yours sincerely

Bill Wilson  
Technical Certifier  
For BABT TCB

