



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 28, 2004

RE: FCC ID: R7NZIP4X5_ATCB001531

Attention: [Mark Briggs](#)

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. FYI – Please note that the block diagram spoken of in 2.1033 should be of the transmitter not the system. This would be the block diagram of the internal workings of the Bluetooth module.
2. Please show both sides of all boards in the internal photos.
3. Please provide an attestation letter for RSS102 compliance.

Dennis Ward

<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.