

Response to TCB Findings

1. Please supply an internal photo of the PCB side of the main board that the transmitter sits on.

Attached.

2. Has a fresh battery been used throughout the entire testing and has the device been tested in 3 orthogonal planes? Please clarify.

A fresh battery was used and the device was maximized in all orientations. Revised Report attached.