
To: monica; leon
Subject: RE: TSANN KUEN GROUP, FCC ID: RBJ-TSKM840X, Assessment NO.: AN05T5082, Notice#1

From: monica
Sent: Tuesday, August 23, 2005 2:12 AM
To: Helen Zhao; leon
Subject: Re: TSANN KUEN GROUP, FCC ID: RBJ-TSKM840X, Assessment NO.: AN05T5082, Notice#1

Dear Helen,

Question #1: The test report (page 4) indicates that all the four test samples use the same Fan motor: Heng Cheng, Type No. YJF62A-120, while the model difference table indicates that other two fan motors 1) Tsann Kuen, Type No. TKM-M01 2) Tsann Kuen, Type No. TKM-M02 will be used alternatively. Please explain why no test configuration using the other two options was ever selected for compliance testing.

Answer #1: The three fan motors have been previewed to identify the worst case for the final test. The worst case (Heng Cheng, Type No. YJF62A-120) was selected to test and report in this report for compliance testing.

Question #2: Please explain the model difference between TSK-8403EMM and TSK-8403E, and TSK-8404EMM and TSK-8404E.

Answer #2: TSK-8403EMM and TSK-8403E are identical except model no., TSK-8404EMM and TSK-8404E are identical except model no. I have reviewed test report. (Page 4). Attached please find revised test report.

Question #3: Please check page 81 for configuration of TSK-8402AMM, it does not agree with description in other sections of the test report.

Answer #3: I have reviewed test report. (Page 81). Attached please find revised test report. Page 81).

Thank you very much for your assistance

Best Regards
Monica Chang