Photographs of EUT

(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 1 of 141



Report No.: 25030004







Cerpass Technology Corp.


Issued Date : May 16, 2025


Page No. : 2 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 3 of 141



Report No.: 25030004

(New addition iron shell) For ESY10I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 4 of 141



(New addition iron shell)





Cerpass Technology Corp.

Issued Date : May 16, 2025

Report No.: 25030004


Page No. : 5 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 6 of 141



Report No.: 25030004

(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 7 of 141



(New addition iron shell)
For ESY10I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 8 of 141



(New addition iron shell) For ESY15I1E, Built-in PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 9 of 141



Report No.: 25030004








Cerpass Technology Corp.


Issued Date : May 16, 2025 Page No. : 10 of 141



Report No.: 25030004

(New addition iron shell) For ESY15I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 11 of 141

Page No.



(New addition iron shell)
For ESY15I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Report No.: 25030004

Page No. : 12 of 141



(New addition iron shell)
For ESY15I1E, Without PoE






Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 13 of 141

Report No.: 25030004



Report No.: 25030004 (New addition iron shell)





Cerpass Technology Corp.


Issued Date : May 16, 2025


Page No. : 14 of 141



Report No.: 25030004

(New addition iron shell)
For ESY15I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Page No. : 15 of 141



(New addition iron shell)
For ESY15I1E, Without PoE





Cerpass Technology Corp.


Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 16 of 141



(New addition iron shell) For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025 Page No. : 17 of 141

Report No.: 25030004



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


: 18 of 141


Page No.



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Built-in PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Page No. : 19 of 141



For ESY22I1E, Built-in PoE

(New addition iron shell)



Cerpass Technology Corp.


Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 20 of 141



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025
Page No. : 21 of 141

Report No.: 25030004



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025


Page No. : 22 of 141



Report No.: 25030004

(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

: 23 of 141

Page No.



(New addition iron shell)
For ESY22I1E, Without PoE





Cerpass Technology Corp.

Issued Date : May 16, 2025

Report No.: 25030004

Page No. : 24 of 141