

NETSCOUT

December 27, 2016

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: RD7-SENSOR4X1

Applicant: NetScout Systems Inc

Dear Examiner,

This is to request a Class II Permissive change for FCC ID: RD7-SENSOR4X1 originally granted on 09/18/2013.

The change under this application is to:

1. Update UNII Bands to new Rules
2. New top cover with additional venting holes and heat spreader to dissipate the thermals.

I attest that the certified device will not be capable of ad-hoc mode operation outside of the grant conditions.

Sincerely,



Tony Ho

Program Manager, Certifications
NetScout Systems Inc
178 E. Tasman Drive
San Jose, CA 95134
Tony.ho@micomlabs.com
408-585-6419
408-585-6899