
Appendix C. Photographs of Setup

Conducted Emission

Mode 1



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Oct. 15, 2007
Report Version : Rev. 02

Report No.: FR791302A



SIDE VIEW

Mode 2



FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Oct. 15, 2007
Report Version : Rev. 02





REAR VIEW




SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Oct. 15, 2007
Report Version : Rev. 02



Radiation Emission



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Oct. 15, 2007
Report Version : Rev. 02