Label of Model: 28559


| Fan Accessory Damp Location Light Kit | 120 VAC,60Hz,42W | Model:28559 | SKU#XXX-XXX | UPC#082392285593 | Conforms To ULSTD.1598 | Certified To CSA STD.C22.2 No.250.0 | 2x Max. Spiral Type 14W CFL bulb |

Vendor No.: 219030 FCC ID:RGB-ADBTLK2855X Made in China 03/14

CAUTION To reduce the risk of fire and electric shock, specified in the install light kit only on ceiling fan models specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.





Label of Model: 28556

Fan Accessory Damp Location Light Kit 120 VAC,60Hz, 42W Model:28556 SKU#XXX-XXX UPC#08239228556 Conforms To UL STD. 1598 Certified To CSA STD. C22.2 No. 250.0 2x Max. Spiral Type 14W CFL bulb

CAUTION To reduce the risk of fire and electric shock, install light kit only on ceiling fan models specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Vendor No.:11688 FCC ID:RGB-ADBTLK2855X Made in China 03/14



Label of Model: 28557

Fan Accessory Damp Location Light Kit 120 VAC,60Hz, 42W Model:28557 SKU#XXX-XXX UPC#082392285579 Conforms To UL STD.1598 Certified To CSA STD.C22.2 No.250.0 2x Max. Spiral Type 14W CFL bulb

CAUTION To reduce the risk of fire and electric shock, install light kit only on ceiling fan models ied in the installation instruction included in this carton

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference,

Vendor No.: 219030 FCC ID:RGB-ADBTLK2855X Made in China 03/14

3160823



and (2) this device must accept any interference received, including interference that may cause undesired operation.

Label of Model: 28558

Fan Accessory Damp Location Light Kit 120 VAC,60Hz,42W Model:28558 SKU#XXX-XXX UPC#082392285586 Conforms To UL STD. 1598 Certified To CSA STD. C22.2 No. 250.0 2x Max. Spiral Type 14W CFL bulb

CAUTION To reduce the risk of fire and electric shock, specified in the install light kit only on ceiling fan models specified in the installation instruction included in this carton.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Vendor No.: 219030 FCC ID:RGB-ADBTLK2855X Made in China 03/14



Intertek 3160823