

ENGLISH Version

FCC/ISED Notice:

This is a CONSUMER device.

- BEFORE USE, you MUST REGISTER THIS DEVICE with your wireless provider and have your provider's consent. Most wireless providers consent to the use of signal boosters. Some providers may not consent to the use of this device on their network. If you are unsure, contact your provider.
- In Canada, BEFORE USE, you must meet all requirements set out in ISED CPC-2-1-05
- You MUST operate this device with approved antennas and cables as specified by the manufacturer. Antennas MUST be installed at least 20 cm (8 inches) from any person.
- You MUST cease operating this device immediately if requested by the FCC (or ISED in Canada) or a licensed wireless service provider.
- WARNING. E911 location information may not be provided or may be inaccurate for calls served by using this device.

Link to ISED CPC-2-1-05:

https://www.ic.gc.ca/eic/site/smt-gst.nsf/eng/h_sf06136.html

➔ CPC-2-1-05 - Zone Enhancers

FCC RF Exposure Statement

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. End users must follow the specific operating instruction for satisfying RF exposure compliance. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

Any changes or modifications not expressly approved by Molex could void the user's authority to operate this equipment.

FCC ID: RK7MBC-NAR2

IC 4774A-MBCNAR2

FRENCH Version

Pour les enrichisseurs de zone de consommation:

Ce produit est un appareil de CONSOMMATION.

- AVANT DE L'UTILISER, vous DEVEZ conformer à toutes les exigences établies dans la CPC-2-1-05.
- Vous DEVEZ utiliser cet appareil avec des antennes et des câbles approuvés, conformément aux indications du fabricant. Les antennes DOIVENT être installées à au moins 20 cm d'une personne.
- Vous DEVEZ cesser d'utiliser cet appareil immédiatement à la demande d'ISDE ou d'un fournisseur de services sans fil autorisé.
- AVERTISSEMENT: Les renseignements relatifs à l'emplacement du service E911 pourraient être non fournis ou inexacts pour les appels effectués au moyen de cet appareil.

lien vers la CPC-2-1-05 d'ISDE:

https://www.ic.gc.ca/eic/site/smt-gst.nsf/fra/h_sf06136.html

➔ CPC-2-1-05 - Enrichisseurs de zone

Les changements ou modifications non approuvés expressément par Molex peuvent entraîner la caducité de l'autorisation d'utiliser l'équipement.

FCC ID: RK7MBC-NAR2

IC 4774A-MBCNAR2