

1 . Label shows an “O” the test report and 731 show a “0” in the FCC ID number. Please confirm which is correct.

Response: FCC ID: RNII614188096T It is ought to “0”.

2 . Page 2 of the test report states that testing it to Part 15.227 instead of 15.239. Please correct.

Response: Have been revised.

3 . Occupied Bandwidth need to include lower Bandedge 88.1 MHz to show compliance with the lower Bandedge of 88 – 108 MHz band. Please revise test report to include this plot.

Response: Have been revised.