
Electrical Block Diagrams

PC mouse X, Y, Z
Axis directional inputs
And 3 button inputs
Note:
Input mechanism by
Means of
press/release
type of switches



Receiving END

