


# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**





# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**





# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**




# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**





# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**





# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**




# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

(Internal)




# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**




# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

**(Internal)**



# INTERTEK TESTING SERVICE

Report No.: 17100010HKG-001

## Equipment Photographs

(Internal)

