

Cellphone-Mate Inc. dba SureCall

Feb 06, 2025

Subject: Tuning and Adjustment of Signal booster, FCC ID: RSN-F4HULTRA

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Dennis Findley

Dennis Findley