


# Mission Microsystems, Inc. <http://www.missionmicro.com/>



5942 Edinger Ave. Suite #113-PMB719, Huntington Beach, CA 92649-1773

(714)-841-1986 FAX: (714)-841-1036

EMAIL: <mailto:mrmicro@missionmicro.com>

February 6, 2004 1 Page

**ATTN: To whom it may concern**

**CC:**

**From: Bill McDonough**

**SUBJECT: McTier Break Guard Transmitter modifications**


---

Based upon results obtained during FCC Part 15 compliance testing at Compatible Laboratories on January 30, we will make the following changes before commencing production.

R2 was 100 ohms, now 47 ohm +-5%.

C7 was 1000pF now 0.1uF

Sincerely,



William B. McDonough

President