



Report No.: 04058792
Charging


Tested By: Hong, Report No.: 04058792

Scan Settings (1 Range)

Frequencies			Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO LN OFF	60dB

Final Measurement: x QP / + AV
Mess Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





ETL SEMKO

Report No.: 04058792
Charging

Tested By: Hong, Report No.: 04058792

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A