

# SparkLAN Communications, Inc

8F., No.257, Sec. 2, Tiding Blvd., Neihu District, Taipei City 11493, Taiwan

TEL: 886-2-2659-1880

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Date: 2016-04-26

Reference: FCC ID: RYK-WPEA251NBT

To The Commission:

This Change of Identification request applies for a new FCC ID: **RYK-WPEA251NBT** as established in 47CFR 2.933(b) for a currently approved device. This application by **SparkLAN Communications, Inc.** will establish a new FCC ID under RYK grantee code for purpose of marketing. The original grant to FCC ID: **PPD-AR5B22** will remain in effect.

An authorization letter by **Qualcomm Atheros, Inc.** is attached.  
Per 2.933(b)

1. The original identification is FCC ID: **PPD-AR5B22**
2. The original grant date is list as below:

Grant Equipment Code	Grant Issue Date
DSS	<b>02/03/2012</b>
DTS	<b>02/03/2012</b>
JBP	<b>02/03/2012</b>
NII	<b>11/16/2015</b>

3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

# SparkLAN Communications, Inc

8F., No.257, Sec. 2, Tiding Blvd., Neihu District, Taipei City 11493, Taiwan

TEL: 886-2-2659-1880


The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely yours,

A handwritten signature in black ink that reads "Robert Wang". The signature is written in a cursive style and is positioned above a horizontal dashed line.

Robert Wang / Executive Assistant to CEO

SparkLAN Communications, Inc.

Tel.: +886-2-2659-1880 ext.340

Fax: +886-2-2659-5538

robert.wang@sparklan.com