




American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

April 26, 2005

RE: FCC ID: S2G-SC100\_ATCB002356  
Attention: Rick McMurray / Kathy Grzovic

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that while the report says no modifications to the device were made, the internal photos show a strip of copper tape on the transmitter section. Is this an engineering fix required for compliance? If so, please either provide a letter attesting that this will be implemented as shown in the final product or please verify that this is an existing assembly item.



Dennis Ward  
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.