

09 May 2008
Ref: US-000182

To FCC

BABT
Balfour House, Churchfield Road
Walton on Thames
Surrey, KT12 2TD
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201
Direct Dial: +44 (0)1932 251261
E-mail: Vina.Kerai@babt.com
Website: www.babt.com

**Overall Assessment Letter for HD Traffic Module
FCC id: S4L-HDTM**

I have reviewed this application and find it compliant.

This is an application for a modular transmitter which supports GSM 850 and PCS 1900. The module additionally supports GSM 900 and DCS 1800, however are not relevant as they are not supported in North America.

Please note the following:

1: Label

The label initially contained an incorrect model name and was therefore updated to state the correct model name. The label placement exhibit shows an incorrect model name, however the exhibit shows the correct FCC ID and is meant to show the label placement.

2: Attestation Letter

An attestation letter has been provided by the Grantee confirming that the declaration of conformity route is being followed in accordance with CFR 47, Part 15 Subpart B for the Class B peripheral portion of the equipment authorization.

3: Test Report

The test report did not have the required signatures for the authorised supervisor of tests. The test report was subsequently corrected to include the required signature. The test lab have also provided a letter in support of their testing to account for the lack of GPRS mode tests which were not provided in the test report.

I underwent the FCC RF exposure training at BABT in July 2007.

Yours sincerely



Vina Kerai
Compliance Engineer, BABT