



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 22, 2005

RE: Pepper Computer Inc.

FCC ID: S5Y1234

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Was EIRP remeasured by MET. If not, what steps were taken to ensure the device was at maximum power equal to or greater than that measured during EMC testing.
- 2) Is the most recent Probe Calibration data provided. The SAR probe calibration > 1 Year. Please explain.
- 3) It is recommended that the testing addendum be updated to include tabular information regarding the Validation and the results.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.