

Multiway Electrical Ind (Shenzhen) Co., Ltd.


Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Rd.
Columbia, MD

Date: April 23,2013
FCC ID: S87BB-56

Dear Sir/Madam:

IC1(RX3301A) employs a oscillator 435.72MHz which is not the receiving operation frequency. This oscillator has nothing to do with the operation frequency. It only drives IC1 to work. Well, Pins 16 and 17 of IC1 make the receiving operation frequency by Adjusting L1 and C4 .

Sincerely,


Signature
Jason Yang / Engineer
Typed name and Title