

Helen Zhao

Subject: FW: ?: FW: NHJ LIMITED, FCC ID: S9VVHD-5500EAR, Assessment NO.: AN05T4841, Notice#1

From: amanda@ccsemc.com.tw [mailto:amanda@ccsemc.com.tw] **On Behalf Of** application@ccsemc.com.tw

Sent: Tuesday, June 07, 2005 7:26 PM

To: Helen Zhao

Subject: ?: FW: NHJ LIMITED, FCC ID: S9VVHD-5500EAR, Assessment NO.: AN05T4841, Notice#1

Question #1: The schematic provided in the filing seems an incompletely one. The operational description indicates it uses CSR BC358239A bluetooth chipset, but the chipset does not even show up on the schematic (CSR BC358239A is not a 34-pin chip). Please explain.

Ans: Please refer to the P5 for update schematic as attachment.

Question #2: The internal photos do not clearly show CSR BC358239A bluetooth chipset. Please provide a bigger and more clear photo.

Ans: The internal photos had been revised, please see P3 as attachment.

Best Regards,

[Amanda](#)