

TRENDware International Inc.
20675 Manhattan Place, Torrance, CA 90501 USA

TEL: 1-(310)-961-5500 FAX: 1-(310)-961-5511

Date: 01.17.2008

41
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner / Review Engineer
Subject: Request to change in identification per section 2.933 of FCC rules
Reference: FCC ID: **SI5WAP372L**

To The Commission:

This Change of Identification request applies for a new FCC ID: **S9ZTEW637AP** as established in 47CFR 2.933(b) for a currently approved device. This application by TRENDware will establish a new FCC ID under TRENDware grantee code for purpose of marketing. The original grant to U-MEDIA Communications, Inc. will remain in effect.

An authorization letter by U-MEDIA Communications, Inc. is attached.

Per 2.933(b)

1. The original identification is **SI5WAP372L**.
2. The original grant date is **01/16/2008**.
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter
External Photos
FCC ID label format and location

Sincerely yours,



Wen Tsai / Product Manager
TRENDware International Inc.
TEL: 1-(310)-626-6252 / FAX: 1-(310)-626-6267 / E-mail: w.tsai@trendnet.com