

Dear Sir/Madam,

Re.: Change statements for FCC ID: SMFPC81007

We, TÜV Product Service Shenzhen Branch, hereby states that for FCC ID: SMFPC81007, the follow 2 contents in test report: 68/850.9.012.01 and 68.850.9.008.01 were revised.

1. In the page 4 of report 68/850.9.012.01, the Rating input of adaptor " 100-240V ~50/60Hz 0.65A MAX" was revise to "100-240V ~50/60Hz 1.0A MAX"
2. In the page 4 of report 68.850.9.008.01, the Rating input of adaptor " 100-240V ~50/60Hz 0.65A MAX" was revise to "100-240V ~50/60Hz 1.0A MAX"


We also declare that the rating of the adaptor using in the FCC testing is "100-240V ~50/60Hz 1.0A MAX", not the "100-240V ~50/60Hz 0.65A MAX".

Thank you for your attention.

(Name & position of the representative)

Paul Yu/EMC Project Manager

(Signature and company chop)

The image shows a handwritten signature in black ink, which appears to be 'Paul Yu', written over a horizontal line. To the right of the signature is a circular company chop stamp. The stamp contains the text 'TUV' in large letters, with 'SIN' below it. The outer ring of the stamp contains the text 'WANGSU TUV PRODUCT SERVICE LTD' and '2007-04-20'.