



# External Photos

## FCC Part 15.247 for FHSS systems/ CANADA RSS-210

FOR:

JACK SERVICE POINT

MODEL #: SP640

WIDERAY CORPORATION  
25 KEARNY STREET—6<sup>TH</sup> FLOOR  
SAN FRANCISCO, CALIFORNIA 94108  
U.S.A

FCC ID: SONSP640TY

IC ID: 5509A-SP640TY

REFERENCE TEST REPORT #: EMC\_1040\_2005\_BLUETOOTH  
DATE: SEPTEMBER 20, 2005



TTI-P-G 081/94-A0  
Accredited according to ISO/IEC 17025



Bluetooth Qualification  
Test Facility  
(BQTF)



Authorized Testing Laboratory

FCC listed # 101450

IC recognized # 3925

**CETECOM Inc.**

411 Dixon Landing Road • Milpitas, CA 95035 • U.S.A.

Phone: + 1 (408) 586 6200 • Fax: + 1 (408) 586 6299 • E-mail: [info@cetecomusa.com](mailto:info@cetecomusa.com) • <http://www.cetecom.com>

CETECOM Inc. is a Delaware Corporation with Corporation number: 2113686

Board of Directors: Dr. Harald Ansorge, Dr. Klaus Matkey, Hans Peter May

© Copyright by CETECOM

**Table of Contents**

1 ASSESSMENT ..... 3

2 EXTERNAL PHOTOS ..... 4

## 1 Assessment

The following is in compliance with the applicable criteria specified in FCC rules Part 15.247 of the Code of Federal Regulations and in compliance with the applicable criteria specified in Industry Canada rules RSS210.

| Company       | Description        | Model # |
|---------------|--------------------|---------|
| WIDERAY CORP. | JACK SERVICE POINT | SP640   |

## 2 EXTERNAL PHOTOS



EUT FRONT



EUT BACK



AC/DC PWR SUPPLY