

Helen Zhao

Subject: FW: TYNTEK CORPORATION, FCC ID: SPP9500TR1, Assessment NO.: AN04T4437, Notice#1



Operational
Description.pdf



External Photo.doc

-----Original Message-----

From: hsieh

Sent: Thursday, December 23, 2004 5:35 PM

To: Helen Zhao

Subject: Re: TYNTEK CORPORATION, FCC ID: SPP9500TR1, Assessment NO.:
AN04T4437, Notice#1

Hi Helen,

Attached please find the revised External Photo and Operational
Description.

Re-Q#1: Please see the new external photo document.

Re-Q#2: The supporting equipment is the Car Alarm Main Board. It support
DC
power and signal to 2-Way Transceiver. Detailed description please see
the
revised Operation Description.

Re-Q#3: Please see the new Operation Description.

Best regards and Merry X'mas .

Joe

-----Original Message-----

From: Compliance Certification Services [mailto:hzhao@ccsemc.com]

Sent: Thursday, December 23, 2004 3:48 PM

To: Helen Zhao

Subject: TYNTEK CORPORATION, FCC ID: SPP9500TR1, Assessment NO.:
AN04T4437, Notice#1

Question #1: Please check the External photos. Only one photo can be
properly displayed.

Question #2: The setup photos show the transmitter was tested with other
supporting equipment. Please explain what kind of supporting equipment
was
used.

Question #3: The Operational Description is not related to this filing.
Please resubmit.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.