## Appendix C. Set up Photograph

## Conducted Emission



FRONT VIEW




**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Dec. 12, 2006
Report Version : Rev. 01

Report No.: FR6D0809





SIDE VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Dec. 12, 2006
Report Version : Rev. 01



## **Radiation Emission**

Mode 1-6



**FRONT VIEW** 

**REAR VIEW** 

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Dec. 12, 2006
Report Version : Rev. 01





Mode 7-9





**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Dec. 12, 2006
Report Version : Rev. 01