



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10

Occupied Bandwidth / Emission Mask




OCCUPIED BANDWIDTH 850 BAND CH128

Date: 22.DEC.2008 09:13:22




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




OCCUPIED BANDWIDTH 850 BAND CH188

Date: 22.DEC.2008 09:14:36




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10



OCCUPIED BANDWIDTH 850 BAND CH251


Date: 22.DEC.2008 09:15:40



Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




OCCUPIED BANDWIDTH 1900 BAND CH512

Date: 22.DEC.2008 09:17:39




Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




OCCUPIED BANDWIDTH 1900 BAND CH661

Date: 22.DEC.2008 09:18:38




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




OCCUPIED BANDWIDTH 1900 BAND CH810

Date: 22.DEC.2008 09:19:55




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




26dB BANDWIDTH 850 BAND CH128

Date: 22.DEC.2008 09:07:57




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




26dB BANDWIDTH 850 BAND CH188

Date: 22.DEC.2008 09:06:04




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




26dB BANDWIDTH 850 BAND CH251

Date: 22.DEC.2008 08:59:53




Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




26dB BANDWIDTH 900 BAND CH512

Date: 22.DEC.2008 08:48:44




Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




26dB BANDWIDTH 900 BAND CH661

Date: 22.DEC.2008 08:50:36




Report Number: W6M20812-9477-P-2224

FCC ID: SRKWPSPT10




26dB BANDWIDTH 900 BAND CH810

Date: 22.DEC.2008 08:51:56




Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10

Spurious Emissions at Antenna Terminals




Conducted Spurious Emission 850 BAND CH128

Date: 22.DEC.2008 11:32:31




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH128
Date: 22.DEC.2008 11:33:27




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH128
Date: 22.DEC.2008 12:54:24




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH128
Date: 22.DEC.2008 11:36:56




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH128
Date: 22.DEC.2008 11:39:12




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH128
Date: 22.DEC.2008 11:41:40




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH128
Date: 22.DEC.2008 11:43:15




Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 11:20:44




Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 11:21:59



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 12:55:37




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 11:25:36




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 11:30:12




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 11:47:15




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH188
Date: 22.DEC.2008 11:45:34




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 11:56:36




Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 11:57:56




Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 12:56:38



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 12:02:54




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 12:05:16




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 12:07:34




Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND CH251
Date: 22.DEC.2008 12:09:08



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:15:39




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:16:43




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:19:53




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:20:48




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:28:22




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:29:14




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 850 BAND Idle
Date: 22.DEC.2008 12:30:35




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:37:48




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:38:43



Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:39:56



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:41:36




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:42:55




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:45:01




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH512
Date: 22.DEC.2008 12:47:51




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:57:49




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:57:17




Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:56:33



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:55:26




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:54:03




Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:52:58



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH661
Date: 22.DEC.2008 12:50:20




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:08:20




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:09:12




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:09:56




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10



Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:11:27



Worldwide Testing Services(Taiwan) Co., Ltd.


Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:12:34



Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:14:32




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND CH810
Date: 22.DEC.2008 13:16:47




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:28:23




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:27:31




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:26:26




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:25:15




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:24:19




Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10




Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:23:06



Worldwide Testing Services(Taiwan) Co., Ltd.

Report Number: W6M20812-9477-P-2224
FCC ID: SRKWPSPT10



Conducted Spurious Emission 1900 BAND Idle
Date: 22.DEC.2008 13:22:01