


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission



Front View



Rear View

Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004

FCC ID: SXO-SP001
IC: 10016A-SP001


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission



Front View



Rear View

Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004

FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Front View

Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004


FCC ID: SXO-SP001

IC: 10016A-SP001

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 1

Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004

FCC ID: SXO-SP001
IC: 10016A-SP001

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2

Test Report Number: 17031690HKG-001, 17031690HKG-002,
17031690HKG-003, 17031690HKG-004

FCC ID: SXO-SP001

IC: 10016A-SP001