

Federal Communication Commission
Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

January 28, 2005

TO WHOM IT MAY CONCERN

Request for Change in Identification

Pursuant to CFR § 2.1033, **Fiber SenSys, Inc.** hereby requests for change in identification ..

The change is for application with FCC ID: **OIFERMO-482X-PRO** granted on
February 2005

The new FCC ID shall be **SXZMD5D**

There are no changes in design, circuitry or construction. Therefore all data of original grant remains applicable.

The following new exhibits are attached:

- External Photos
- ID label with label location information
- Authorization from original grantee (Cias) to allow the new grantee to do so.

If you have any questions, please feel free to contact us at the address shown below

Sincerely,



Michael Montgomery
Marketing Manager

EMail: Michael.Montgomery@FiberSenSys.com
Mobile Tel: (503) 701-3682