

10/May/2006

Dear Ms Helen

Please transfer comment and circuitry to ATCB investigation

For our model CCB110 already modify to broadcast station no audio signal (without modulation time) stop transmitter operation.

receiver reception carrier signal when unit detect without audio signal time, IC4 MC3361 pin 13 output one distinguish signal via IC6 CD4025 and Q16 8550 transistor to disable transmitter IC power source.

Best Regards

Y.M. Lai (project engineer)

10/May/2006

Email : ymlai88@163.com