



---

AXM0361, AXM-0361

The SMA connector is only applied at the factory to confirm compliance and operation. Modules are shipped with the integral antenna applied and the SMA connector is not functional. The user manual provides a disclaimer that the J104 - SMA Test connector is not to be applied by the user or the FCC registration is void. To apply the SMA connector will require the use of soldering tools to remove the RF shield and modify module components. This is not documented for the user to perform.

Axiom applies the AXM0361 and AXM-0361 as the same part number nomenclature. We can change the module legend to remove the hyphen in the part number if required.

April 25, 2006

A handwritten signature in black ink that reads "Roger D. Forrester".

Signed: \_\_\_\_\_  
Roger D. Forrester

Title: Engineering Manager

---

AXIOM MANUFACTURING  
2813 INDUSTRIAL LN  
GARLAND, TX 75041  
(972) 926-9303 Phone  
(972) 926-6063 Fax  
<http://www.axman.com>