

June 23, 2011

NEMKO CANADA, INC.
303 River Road, Ottawa Ontario
K1V1H2, CANADA

Subject : Revision of test report certified under FCC ID : THCFCS-S5501F

Dear TCB,

We, Nemko Korea, found an error in the test report (No. : NK-11-E-359) that certified under FCC ID : THCFCS-S5501F. It has happened by customer's miss information.

Hereby we re-issue the corrigendum test report according to customer's request. Please be noticed this.

We are kindly ask TCB to accept this revised test report without further action.

We made corrections on page 6 in test report (No. NK-11-E-359) as follows :

Before

Equipment	Model	Manufacturer	Serial Number
Panel	LB506B(55")_MAIN BOARD R01	HUC/KSE	N/A
Main Board	LB506B IO BOARD R01	HUC/KSE	N/A
I/O Board	DT-PB260W	HANSOL	N/A
SMPS	LTI550HJ05	SAMSUNG	N/A

After

Equipment	Model	Manufacturer	Serial Number
Panel	LTI550HJ05	Samsung Electronics or S-LCD	N/A
Main Board	LB506B Main Board	D&T Inc.	N/A
I/O Board	LB506B IO Board	D&T Inc.	N/A
SMPS	DT-PB260W	D&T Inc.	N/A

A revised test report was attached with the e-mail.

Thank you again for your support and service to the Nemko Korea.

Sincerely,

 June. 23. 2011

Hyunho Kim

EMC Manager & Chief Engineer