

Project Number:
Model Number:

08CA62337
VP 4726

File Number

TC8345

Test Report No: 08CA62337-FCC

Date of Issue: January 12, 2009

1. TEST SETUP PHOTOS

Figure 1. Conducted Emission Test Setup for Optical DVI Mode



UL Korea, Ltd
33rd FL, Gangnam Finance Center, 737
Yeoksam-dong, Gangnam-gu, Seoul
135-984 Korea
Tel: +82.2.2009.9000, Fax: +82.2.2009.9405

A not-for-profit organization dedicated
to public safety and committed to
quality service for over 100 years

Project Number:
Model Number:


08CA62337
VP 4726

File Number

TC8345

Test Report No: 08CA62337-FCC
Date of Issue: January 12, 2009

Figure 2. Conducted Emission Test Setup for SDI In/Out Mode



Project Number:
Model Number:


08CA62337
VP 4726

File Number

TC8345

Test Report No: 08CA62337-FCC
Date of Issue: January 12, 2009

Figure 3. Photo of Radiated emission test setup for Optical DVI Mode, 30MHz to 1GHz



Project Number:
Model Number:


08CA62337
VP 4726

File Number

TC8345

Test Report No: 08CA62337-FCC
Date of Issue: January 12, 2009

Figure 4. Photo of Radiated emission test setup for Optical DVI Mode, 1GHz to 2GHz



Project Number:
Model Number:


08CA62337
VP 4726

File Number

TC8345

Test Report No: 08CA62337-FCC
Date of Issue: January 12, 2009

Figure 5. Photo of Radiated emission test setup for SDI In/Out Mode, 30MHz to 1GHz



Project Number:
Model Number:

08CA62337
VP 4726

File Number

TC8345

Test Report No: 08CA62337-FCC
Date of Issue: January 12, 2009

Figure 6. Photo of Radiated emission test setup for SDI In/Out Mode, 1GHz to 2GHz

