

Project Number: 10CA41560
Model Number: VP4726

File Number TC8312

Test Report No: 10CA41560-FCC
Date of Issue: September 13, 2010

TEST SETUP PHOTOS

Figure 1. Conducted Emission Test Setup: DVI In/Out Mode



Project Number: 10CA41560
Model Number: VP4726

File Number TC8312

Test Report No: 10CA41560-FCC
Date of Issue: September 13, 2010

Figure 2. Conducted Emission Test Setup: SDI In/Out Mode




Project Number: 10CA41560
Model Number: VP4726

File Number TC8312

Test Report No: 10CA41560-FCC
Date of Issue: September 13, 2010

Figure 3. Photo of Radiated emission test setup: DVI In/Out Mode, 30 MHz to 1000 MHz




Project Number: 10CA41560
Model Number: VP4726

File Number TC8312

Test Report No: 10CA41560-FCC
Date of Issue: September 13, 2010

Figure 4. Photo of Radiated emission test setup: SDI In/Out Mode, 30 MHz to 1000 MHz




Project Number: 10CA41560
Model Number: VP4726

File Number TC8312

Test Report No: 10CA41560-FCC
Date of Issue: September 13, 2010

Figure 5. Photo of Radiated emission test setup: DVI In/Out Mode, 1.0 GHz to 2.0 GHz



Project Number: 10CA41560
Model Number: VP4726

File Number TC8312

Test Report No: 10CA41560-FCC
Date of Issue: September 13, 2010

Figure 6. Photo of Radiated emission test setup: SDI In/Out Mode, 1.0 GHz to 2.0 GHz

