

Project Number:  
Model Number:

09CA41702  
VP4732

File Number

TC8312

Test Report No: 09CA41702-FCC

Date of Issue: October 7, 2009

## 1. TEST SETUP PHOTOS

Figure 1. Conducted Emission Test Setup



UL Korea, Ltd  
33<sup>rd</sup> FL, Gangnam Finance Center, 737  
Yeoksam-dong, Gangnam-gu, Seoul  
135-984 Korea  
Tel: +82.2.2009.9000, Fax: +82.2.2009.9405

A not-for-profit organization dedicated  
to public safety and committed to  
quality service for over 100 years

Project Number:  
Model Number:

09CA41702  
VP4732

File Number

TC8312

Test Report No: 09CA41702-FCC

Date of Issue: October 7, 2009

**Figure 2. Conducted Emission Test Setup**



Project Number:  
Model Number:

09CA41702  
VP4732


File Number

TC8312

Test Report No: 09CA41702-FCC  
Date of Issue: October 7, 2009

**Figure 5. Photo of Radiated emission test setup for 30MHz to 1GHz**

Test condition: Optical DVI Mode



Project Number:  
Model Number:

09CA41702  
VP4732


File Number

TC8312

Test Report No: 09CA41702-FCC  
Date of Issue: October 7, 2009

**Figure 6. Photo of Radiated emission test setup for 1.0 GHz to 2.0 GHz**

Test condition: Optical DVI Mode



Project Number:  
Model Number:

09CA41702  
VP4732


File Number

TC8312

Test Report No: 09CA41702-FCC  
Date of Issue: October 7, 2009

**Figure 7. Photo of Radiated emission test setup for 30 MHz to 1.0 GHz**

Test condition: SDI In/Out Mode



Project Number:  
Model Number:

09CA41702  
VP4732

File Number

TC8312

Test Report No: 09CA41702-FCC  
Date of Issue: October 7, 2009

**Figure 8. Photo of Radiated emission test setup for 1.0 GHz to 2.0 GHz**

